

General Information

Date & Time: 16, Jan, 2026 09:02

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	18,847
Registration No.	NKH1205	Chassis No.	PAEL65MYSRB024783
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	76.9	77	76	78
2	Boot Lid	154.6	147	159	158
3	Roof	81.1	81	77	88/78
4	Left Front Fender	93.0	118	88	73
5	Left Front Door	75.0	70	70	85
6	Center Panel Left	79.6	84	76	79
7	Left Rear Door				
8	Left Back Panel	148.0	182	143	119
9	Right Front Fender	81.4	83	88	74
10	Right Front Door	74.7	78	66	80
11	Center Panel Right	79.6	79	80	80
12	Right Rear Door				
13	Right Back Panel	156.6	180	133	157

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Trim - Grime - Large / (R) Front Trim - Grime - Large / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / Mat Other - Grime - Small / Overall Interior - Smell - Yes / Sunvisor, Sunglass Holder - Grime - Small / Ceiling - Grime - Small</p>		<p>Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / (L) Side Gate - Repair mark - Yes / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Medium / Front Panel - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Small / (R) Side Gate - Repair mark - Yes / (R) Side Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Side Gate - Scratch & Dent - Small / Rear Gate - Scratch & Dent - Small / (L) Center Panel - Scratch & Dent - Small / Roof - Scratch & Dent - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Reverse Camera - N/A - Yes</p>	

Inspector Notes
with LTO plate, with spare tire, with spare key, with jack, no tools, no reverse camera, no warranty and manual booklet, scratches on taillight and headlight, aircon vent right side weak ventilation.