

General Information

Date & Time: 13, Jan, 2026 17:21

Make	Jetour	Model	Dashing
YOM	2024	Odo Meter Reading	8,586
Registration No.	NKH7486	Chassis No.	HJRPBGFB7RB159296
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	144.3	136	143	154
2	Boot Lid	114.0	112	114	116
3	Roof	131.2	131	117	146/131
4	Left Front Fender	137.6	139	134	140
5	Left Front Door	141.6	139	142	144
6	Center Panel Left				
7	Left Rear Door	135.0	133	136	136
8	Left Back Panel	144.6	138	141	155
9	Right Front Fender	136.6	139	138	133
10	Right Front Door	132.0	131	139	126
11	Center Panel Right				
12	Right Rear Door	128.3	126	135	124
13	Right Back Panel	130.6	131	137	124

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Front Door, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>incomplete tools and spare tire/ with jack/ with warranty booklets and LTO plate/</p>