

General Information

Date & Time: 16, Dec, 2025 15:57

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	42,727
Registration No.	DBM2137	Chassis No.	PA1B18F35R4241312
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.6	119	111	132
2	Boot Lid	115.3	118	106	122
3	Roof	99.9	101	95	100/104
4	Left Front Fender	140.3	118	123	180
5	Left Front Door	102.9	105	104	100
6	Center Panel Left				
7	Left Rear Door	128.6	123	145	118
8	Left Back Panel	114.6	120	110	114
9	Right Front Fender	101.6	100	102	103
10	Right Front Door	105.0	101	96	118
11	Center Panel Right				
12	Right Rear Door	97.5	89	99	104
13	Right Back Panel	111.0	120	101	112

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain Remarks Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Small / Trunk Room - Worked - Minimal / Console, Switchs, Vents - Worked - Minimal	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap Remarks (L) Front Fender - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes

with LTO plate, with warranty & manual booklet, with reverse camera, with spare key, with spare tire, no tools & jack, scratches on taillight.