

General Information

Date & Time: 17, Dec, 2025 18:49

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	48,802
Registration No.	NFH1439	Chassis No.	PA1B18F33M4166246
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.3	102	102	115
2	Boot Lid	100.6	96	101	105
3	Roof	90.6	108	80	88/87
4	Left Front Fender	97.5	94	97	102
5	Left Front Door	102.6	103	102	103
6	Center Panel Left				
7	Left Rear Door	106.3	109	104	106
8	Left Back Panel	111.6	120	109	106
9	Right Front Fender	93.1	100	91	89
10	Right Front Door	94.3	97	91	95
11	Center Panel Right				
12	Right Rear Door	123.6	127	123	121
13	Right Back Panel	182.0	145	133	268

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Small	Remarks (R) Rear Fender - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Minimal / Roof - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/No spare key/No reverse camera/with jack and incomplete tools/No warranty booklet