

General Information

Date & Time: 18, Dec, 2025 08:31

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	96,006
Registration No.	NHG1258	Chassis No.	PA1B18F33P4229706
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.3	157	103	107
2	Boot Lid	112.6	100	128	110
3	Roof	114.9	142	123	88/107
4	Left Front Fender	100.6	100	98	104
5	Left Front Door	106.6	101	108	111
6	Center Panel Left				
7	Left Rear Door	110.3	111	104	116
8	Left Back Panel	126.2	108	177	94
9	Right Front Fender	101.5	105	100	100
10	Right Front Door	106.9	97	100	124
11	Center Panel Right				
12	Right Rear Door	127.0	162	108	111
13	Right Back Panel	149.0	150	137	160

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Minimal / Trunk Room - Worked - Minimal / (R) Front Floor Mat - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal / Dashboard - Worked - Minimal	Remarks (R) Step - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch & Dent - Small / Roof - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, with manual & warranty booklet, with spare tire, with jack, with reverse camera, no tools, no spare key, scratches on taillight.