

General Information

Date & Time: 18, Dec, 2025 08:25

Make	Toyota	Model	Rush
YOM	2023	Odo Meter Reading	20,097
Registration No.	NIN6326	Chassis No.	MHKE8FF2PPK009922
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	92.5	99	82	96
2	Boot Lid	98.8	100	98	99
3	Roof	93.7	87	86	96/107
4	Left Front Fender	95.3	90	96	100
5	Left Front Door	103.9	102	98	112
6	Center Panel Left				
7	Left Rear Door	101.1	105	99	100
8	Left Back Panel	95.3	95	94	97
9	Right Front Fender	102.3	108	100	100
10	Right Front Door	102.1	106	99	102
11	Center Panel Right				
12	Right Rear Door	99.1	98	100	100
13	Right Back Panel	95.1	99	85	101

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key/with jack no tools/with warranty booklet/with reverse camera</p>