

General Information

Date & Time: 17, Dec, 2025 13:13

Make	Toyota	Model	Hiace
YOM	2021	Odo Meter Reading	85,811
Registration No.	CBL5154	Chassis No.	JTFNAFAP5L8017231
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.0	135	116	118
2	Boot Lid	221.6	186	238	241
3	Roof	163.7	151	153	190/161
4	Left Front Fender	142.3	134	155	138
5	Left Front Door	128.6	137	127	122
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	127.6	118	134	131
9	Right Front Fender	141.3	139	142	143
10	Right Front Door	137.6	129	144	140
11	Center Panel Right	136.6	138	141	131
12	Right Rear Door	135.3	136	130	140
13	Right Back Panel	144.3	135	135	163

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Console, Switchs, Vents - Worked - Minimal / Dashboard - Worked - Minimal / (R) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Worked - Small / Trunk Room - Worked - Minimal	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Front Fender, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / Roof - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Repair mark - Yes / (L) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, with spare tire, with jack, no spare key, no warranty & manual booklet, no tools, no reverse camera, check engine indicator on, unusual sound in engine, issue on taillight lens, issue on wiper.