

General Information

Date & Time: 16, Dec, 2025 15:12

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	41,649
Registration No.	NFR8567	Chassis No.	PA1B18F39R4258789
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	110	105	117
2	Boot Lid	106.3	102	110	107
3	Roof	104.9	118	98	96/108
4	Left Front Fender	101.8	100	100	106
5	Left Front Door	110.0	108	112	110
6	Center Panel Left				
7	Left Rear Door	107.3	116	104	102
8	Left Back Panel	115.1	131	116	98
9	Right Front Fender	113.2	111	93	136
10	Right Front Door	111.0	109	121	103
11	Center Panel Right				
12	Right Rear Door	108.6	103	111	112
13	Right Back Panel	106.0	102	105	111

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Medium / Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Floor Mat - Worked - Small	Remarks Member (Bolted) - Dent - Yes / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small / Trunk Hood, Rear Gate - Crack, Gap - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, with jack, incomplete tools, no spare tire, with LTO plate, scratches on tail light