

General Information

Date & Time: 18, Dec, 2025 08:48

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	8,031
Registration No.	NJC7635	Chassis No.	PAHACACA4S6425412
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.6	106	100	108
2	Boot Lid	50.2	58	50	43
3	Roof	116.7	129	133	105/100
4	Left Front Fender	104.6	110	101	103
5	Left Front Door	102.4	99	104	104
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	74.8	62	87	76
9	Right Front Fender	102.3	100	102	105
10	Right Front Door	98.6	94	100	102
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	62.8	55	61	72

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Ceiling - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Rear Gate - Scratch - Small / Cargo Bed Floor - Scratch - Large / (L) Side Gate - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Dent - Minimal / Roof - Rust, Corrosion - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
no warranty booklet, jack and tools, with spare tire, no LTO plate,