

General Information

Date & Time: 18, Dec, 2025 10:16

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	20,916
Registration No.	NKH2036	Chassis No.	MHFAB1BY2R3121295
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.1	83	93	112
2	Boot Lid	104.3	102	92	119
3	Roof	119.2	142	130	100/105
4	Left Front Fender	293.0	452	273	154
5	Left Front Door	118.6	108	127	121
6	Center Panel Left				
7	Left Rear Door	115.3	111	111	124
8	Left Back Panel	119.3	114	105	139
9	Right Front Fender	156.3	132	176	161
10	Right Front Door	109.0	116	110	101
11	Center Panel Right				
12	Right Rear Door	110.3	114	106	111
13	Right Back Panel	133.6	174	108	119

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks</p> <p>Trunk Room - Worn, Scratch, Cut, Crack - Medium / Dashboard - Worked - Minimal / Console, Switchs, Vents - Worked - Minimal / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks</p> <p>(R) Step - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Step - Repair Traces - Yes / Bonnet, Headlight - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Crack, Gap - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / Roof - Scratch & Dent - Small</p>
Frame Evaluation : C	Functional Evaluation : C
<p>Remarks</p> <p>Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks</p> <p>Radiator Water Pump - Leak - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with manual & warranty booklet, with spare tire, with reverse camera, no tools & jack, no spare key, scratches on taillight, issue on headlight & fog lamp.</p>