

General Information

Date & Time: 17, Dec, 2025 15:36

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	48,866
Registration No.	NIC6371	Chassis No.	PA1B18F38N4180872
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.4	110	92	120
2	Boot Lid	103.0	103	102	104
3	Roof	97.6	112	91	97/90
4	Left Front Fender	99.4	93	98	107
5	Left Front Door	101.8	111	98	96
6	Center Panel Left				
7	Left Rear Door	100.6	101	100	101
8	Left Back Panel	109.7	115	98	116
9	Right Front Fender	91.6	100	87	88
10	Right Front Door	99.2	98	101	99
11	Center Panel Right				
12	Right Rear Door	104.6	106	102	106
13	Right Back Panel	102.1	94	101	111

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Medium	Remarks (L) Rear Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Dent - Small / (R) Front Fender, Molding - Crack, Gap - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Dent - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/No spare key/No reverse camera/with jack and incomplete tools/No warranty booklet