

General Information

Date & Time: 22, Dec, 2025 10:19

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	14,392
Registration No.	NFR4144	Chassis No.	PA1B18F36R4248415
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.3	121	110	115
2	Boot Lid	99.7	101	98	100
3	Roof	96.3	94	100	90/101
4	Left Front Fender	96.5	99	97	94
5	Left Front Door	98.6	98	98	100
6	Center Panel Left				
7	Left Rear Door	100.3	98	100	103
8	Left Back Panel	107.3	111	107	104
9	Right Front Fender	97.0	96	98	97
10	Right Front Door	98.3	98	96	101
11	Center Panel Right				
12	Right Rear Door	100.1	95	102	103
13	Right Back Panel	102.6	102	97	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Large / (L) Front Trim - Grime - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet and LTO plate/ with jack and spare tire/ with tools/</p>