

General Information

Date & Time: 19, Dec, 2025 15:53

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	56,331
Registration No.	DBQ1214	Chassis No.	PA1B18F39R4267556
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	164.0	164	161	167
2	Boot Lid	129.3	116	151	121
3	Roof	116.2	111	110	133/111
4	Left Front Fender	123.6	160	101	110
5	Left Front Door	110.0	117	103	110
6	Center Panel Left				
7	Left Rear Door	109.1	123	98	106
8	Left Back Panel	139.3	127	116	175
9	Right Front Fender	110.0	112	110	108
10	Right Front Door	108.3	110	109	106
11	Center Panel Right				
12	Right Rear Door	184.6	202	184	168
13	Right Back Panel	184.3	169	178	206

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Grime - Small / Dashboard - Worked - Minimal / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Rear Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Roof - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with spare tire, with reverse camera, with inc tools & jack, with manual booklet, no spare key, no warranty booklet, scratches on taillight.</p>