

## General Information

Date & Time: 18, Dec, 2025 15:32

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	58,474
<b>Registration No.</b>	NKI6539	<b>Chassis No.</b>	PA1B18F39R4264365
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.0	120	111	138
2	Boot Lid	107.0	102	108	111
3	Roof	118.0	124	114	112/122
4	Left Front Fender	103.3	98	106	106
5	Left Front Door	112.0	114	119	103
6	Center Panel Left				
7	Left Rear Door	116.6	114	117	119
8	Left Back Panel	119.6	121	127	111
9	Right Front Fender	119.3	110	141	107
10	Right Front Door	117.3	109	130	113
11	Center Panel Right				
12	Right Rear Door	113.0	115	110	114
13	Right Back Panel	112.3	114	106	117

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 1.5em;">C</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 1.5em;">E</span>
<p><b>a :</b> Cut, Fray <b>d :</b> Loose, Deformed <b>k :</b> Animal Hair <b>s :</b> Smell <b>t :</b> Cigarette Burns <b>x :</b> Defective <b>y :</b> Stain</p>	<p><b>A :</b> Scratch <b>AU :</b> Scratch &amp; Dent <b>B :</b> Modified <b>C :</b> Corrosion <b>G :</b> Stone chip <b>P :</b> Faded <b>S :</b> Rust <b>SC :</b> Rust &amp; Corrosion <b>U :</b> Dent <b>X :</b> Defective <b>Y :</b> Crack, Gap</p>
<p><b>Remarks</b>  (L) Front Floor Mat - Cut, Crack - Small / (L) Front Floor Mat - Worked - Large / (R) Front Floor Mat - Worked - Small / Mat Other - Missing - Yes / Overall Interior - Animal Hair - Yes / (L) Front Seat - Worn - Yes / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (R) Rear Trim - Cut, Crack - Small / Ceiling - Grime - Minimal</p>	<p><b>Remarks</b>  Front Bumper, Grille, Lamps - Modified - Small / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch, Peeled - Yes / (R) Front Door, Molding - Scratch &amp; Dent - Medium / (R) Rear Door, Molding - Scratch &amp; Dent - Medium / (R) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Medium / Member (Bolted) - Dent - Yes / Bonnet, Headlight - Dent - Medium / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Roof - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="color: red; font-size: 1.5em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 1.5em;">A</span>
<p><b>Remarks</b>  Defects not found</p>	<p><b>Remarks</b>  Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<b>Inspector Notes</b>
with warranty booklet, with jack, incomplete tools, with spare tire, with LTO plate, scratches on tail light, plate light issue