

General Information

Date & Time: 22, Dec, 2025 13:20

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	6,875
Registration No.	NKA9430	Chassis No.	PA1B18F31R4242375
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.6	127	105	124
2	Boot Lid	113.3	115	117	108
3	Roof	118.0	132	110	110/120
4	Left Front Fender	106.0	105	106	107
5	Left Front Door	109.6	114	110	105
6	Center Panel Left				
7	Left Rear Door	111.0	107	116	110
8	Left Back Panel	114.6	117	114	113
9	Right Front Fender	107.3	111	105	106
10	Right Front Door	108.6	110	108	108
11	Center Panel Right				
12	Right Rear Door	111.0	106	108	119
13	Right Back Panel	112.6	110	113	115

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Large / Rear Seat - Grime - Large / (L) Front Floor Mat - Worked - Large</p>	<p>Remarks Bonnet - Repair Traces - Yes / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Crack, Gap - Large / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no LTO plate/ possible flooding/ no tools and warranty booklet/ with spare tire and jack/</p>