

General Information

Date & Time: 22, Dec, 2025 13:55

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	9,936
Registration No.	NKA5721	Chassis No.	PA1B18F38R4244429
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.3	107	106	106
2	Boot Lid	106.2	97	110	112
3	Roof	97.3	96	98	96/100
4	Left Front Fender	108.3	113	102	110
5	Left Front Door	143.6	139	150	142
6	Center Panel Left				
7	Left Rear Door	149.0	153	146	148
8	Left Back Panel	104.3	110	103	100
9	Right Front Fender	145.3	144	141	151
10	Right Front Door	101.0	100	102	101
11	Center Panel Right				
12	Right Rear Door	106.6	102	107	111
13	Right Back Panel	103.7	105	95	111

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / (L) Front Door, Molding - Dent - Small / (L) Rear Door, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Dent - Small / Bonnet, Headlight - Scratch - Large / (L) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Rust, Corrosion - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>no LTO plate/ incomplete tools/ with jack and spare tire/ with warranty booklet/</p>