

General Information

Date & Time: 19, Dec, 2025 15:45

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	46,853
Registration No.	NGQ3570	Chassis No.	PA1B18F30N6008064
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	108	100	113
2	Boot Lid	138.3	125	131	159
3	Roof	96.4	106	90	84/106
4	Left Front Fender	96.3	97	100	92
5	Left Front Door	100.5	100	105	97
6	Center Panel Left				
7	Left Rear Door	99.6	102	100	97
8	Left Back Panel	106.6	122	102	96
9	Right Front Fender	90.1	93	97	81
10	Right Front Door	97.6	102	97	94
11	Center Panel Right				
12	Right Rear Door	124.6	133	116	125
13	Right Back Panel	133.0	140	112	147

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Medium / (L) Front Trim - Worked - Small / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Small / Rear Seat - Grime - Small / Steering Wheel - Worn, Peel, Crack - Medium</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>with warranty booklet, jack and tools, with spare tire, with LTO plate, scratches on tail light and headlight</p>