

General Information

Date & Time: 05, Jan, 2026 18:41

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	30,252
Registration No.	NKE8266	Chassis No.	PA1B18F37R4265370
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.7	108	92	111
2	Boot Lid	99.2	95	96	107
3	Roof	140.2	264	95	101/101
4	Left Front Fender	95.7	92	97	98
5	Left Front Door	103.5	105	114	92
6	Center Panel Left				
7	Left Rear Door	96.4	100	98	92
8	Left Back Panel	102.7	110	100	98
9	Right Front Fender	107.3	108	110	104
10	Right Front Door	145.3	100	104	232
11	Center Panel Right				
12	Right Rear Door	102.0	102	101	103
13	Right Back Panel	106.2	100	100	119

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / Dashboard - Loose, Deformed - Minimal / Ceiling - Crinkle - Minimal / Rear Seat - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Roof - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate, with Manual & warranty booklet, with reverse camera, with spare tire, with spare key with inc tools & jack, scratches on taillight & headlight, unusual sound at the bottom.</p>