

General Information

Date & Time: 06, Jan, 2026 12:56

Make	Toyota	Model	Hilux
YOM	2025	Odo Meter Reading	8,153
Registration No.	NKO9944	Chassis No.	MR0JB8DD7S3236691
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	132.3	127	138	132
2	Boot Lid	103.4	94	112	104
3	Roof	118.2	120	113	117/123
4	Left Front Fender	128.0	139	130	115
5	Left Front Door	112.0	117	111	108
6	Center Panel Left				
7	Left Rear Door	111.0	116	109	108
8	Left Back Panel	118.0	121	117	116
9	Right Front Fender	127.0	139	121	121
10	Right Front Door	108.3	110	104	111
11	Center Panel Right				
12	Right Rear Door	111.3	108	108	118
13	Right Back Panel	110.6	112	114	106

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Rear Trim - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Worked - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Rear Gate - Scratch - Minimal / (L) Side Gate - Scratch & Dent - Large / (L) Center Panel - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack and tools, with spare tire and LTO PLATE, scratched and cracked tail light</p>