

## General Information

Date & Time: 05, Jan, 2026 13:45

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	6,139
Registration No.	NHU7818	Chassis No.	PA1B18F39R4276452
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.6	135	100	118
2	Boot Lid	115.3	105	125	116
3	Roof	106.5	112	106	107/101
4	Left Front Fender	124.0	105	163	104
5	Left Front Door	103.3	103	104	103
6	Center Panel Left				
7	Left Rear Door	111.0	108	110	115
8	Left Back Panel	115.3	114	121	111
9	Right Front Fender	115.0	116	116	113
10	Right Front Door	108.0	111	108	105
11	Center Panel Right				
12	Right Rear Door	112.0	109	112	115
13	Right Back Panel	116.0	104	114	130

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>C</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Ceiling - Grime - Small / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Grime - Minimal</p>		<p><b>Remarks</b> Roof - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Door, Molding - Modified - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Modified - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch &amp; Dent - Small / (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
with LTO plate, with manual & warranty booklet, with reverse camera, with inc tools & jack, with spare tire, no spare key, headlight and taillight scratches.