

General Information

Date & Time: 06, Jan, 2026 14:00

Make	Toyota	Model	Innova
YOM	2025	Odo Meter Reading	15,770
Registration No.	EAG8027	Chassis No.	PA2JA8EM0R0148870
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.0	108	106	83
2	Boot Lid	106.6	111	109	100
3	Roof	92.7	91	104	82/95
4	Left Front Fender	126.3	106	107	166
5	Left Front Door	105.8	100	114	104
6	Center Panel Left				
7	Left Rear Door	106.6	106	112	102
8	Left Back Panel	194.3	254	170	159
9	Right Front Fender	103.9	96	108	108
10	Right Front Door	100.3	101	100	100
11	Center Panel Right				
12	Right Rear Door	100.6	96	100	106
13	Right Back Panel	119.6	117	117	125

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Smell - Yes / (R) Front Seat - Grime - Medium / Glove Box - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Worn - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Worked - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Small / Rear Seat - Grime - Small / (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Grime - Small</p>	<p>Remarks (L) Rear Fender - Repair Traces - Yes / Roof - Scratch - Large / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Crack, Gap - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>no warranty booklet, jack and tools, with spare tire, no LTO plate, possible flooding, scratches on headlight and tail light</p>