


General Information

Date & Time: 20, Dec, 2025 14:55

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	16,269
Registration No.	NJC6259	Chassis No.	PAHACACA5S6424804
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.8	100	153	95
2	Boot Lid	97.3	99	92	101
3	Roof	97.7	102	97	101/92
4	Left Front Fender	99.8	103	99	98
5	Left Front Door	100.6	101	100	101
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	100.4	102	99	100
9	Right Front Fender	95.5	92	95	100
10	Right Front Door	90.7	93	91	88
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	94.2	94	94	94

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Smell - Yes / Ceiling - Grime - Large / Dashboard - Traces of Adhesive Tape - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Side Gate - Scratch & Dent - Small / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (R) Side Gate - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Cargo Bed Floor - Scratch & Dent - Small / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Small / (R) Mirror - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire and Jack, No Tools and warranty booklet, No spare key, worn tires and Sparetire, No reverse camera, foul smell, Plate light and Room light issue, air-conditioned issue.</p>