

General Information

Date & Time: 06, Jan, 2026 15:54

Make	Toyota	Model	Veloz
YOM	2024	Odo Meter Reading	14,529
Registration No.	GBF1395	Chassis No.	MHFAB1BY9R3103683
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Pearl White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	111	107	125
2	Boot Lid	113.0	101	129	109
3	Roof	135.2	146	145	125/125
4	Left Front Fender	122.0	129	117	120
5	Left Front Door	133.6	129	129	143
6	Center Panel Left				
7	Left Rear Door	126.6	134	122	124
8	Left Back Panel	140.3	138	142	141
9	Right Front Fender	123.6	125	128	118
10	Right Front Door	125.3	131	125	120
11	Center Panel Right				
12	Right Rear Door	121.0	122	115	126
13	Right Back Panel	137.3	122	139	151

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Small / (R) Front Floor Mat - Grime - Minimal	Remarks (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
With warranty booklet, spare tire and jack. Without tools and seat cover. 1 key. With LTO plate.