


General Information

Date & Time: 29, Dec, 2025 14:17

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	35,087
Registration No.	CBD8930	Chassis No.	PA1B18F37N4154704
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	120	103	117
2	Boot Lid	211.0	153	146	334
3	Roof	93.8	104	88	97/86
4	Left Front Fender	105.3	104	105	107
5	Left Front Door	103.2	110	105	95
6	Center Panel Left				
7	Left Rear Door	128.6	124	132	130
8	Left Back Panel	114.6	125	106	113
9	Right Front Fender	103.6	107	98	106
10	Right Front Door	102.6	100	108	100
11	Center Panel Right				
12	Right Rear Door	105.0	107	101	107
13	Right Back Panel	106.0	101	106	111

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Minimal</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Roof - Scratch - Minimal / Front Windshield - Scratch, Stone chip - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With Lto plate, with jack and tools, 1key, no warranty booklet and spare tire, scratches on headlights and taillight</p>