

General Information

Date & Time: 23, Dec, 2025 14:09

Make	Toyota	Model	Avanza
YOM	2023	Odo Meter Reading	36,046
Registration No.	NHA2743	Chassis No.	MHFAA1BY4P0016047
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.0	106	105	107
2	Boot Lid	117.4	123	130	99
3	Roof	110.7	122	113	105/103
4	Left Front Fender	109.3	107	107	114
5	Left Front Door	113.3	114	107	119
6	Center Panel Left				
7	Left Rear Door	149.3	125	146	177
8	Left Back Panel	171.6	226	166	123
9	Right Front Fender	106.6	104	106	110
10	Right Front Door	109.6	109	107	113
11	Center Panel Right				
12	Right Rear Door	113.6	116	110	115
13	Right Back Panel	111.3	110	107	117

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Mat Other - Grime - Small / Ceiling - Grime - Medium / (L) Front Floor Mat - Grime - Small</p>	<p>Remarks (L) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Repair mark - Difference in Color / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Repair mark - Difference in Color / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with spare tire and jack, 1key, no tools, both side mirror issue-loose,</p>