

## General Information

Date & Time: 12, Jan, 2026 18:56

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2026	<b>Odo Meter Reading</b>	2,682
<b>Registration No.</b>	CCQ4676	<b>Chassis No.</b>	PA1B18F32S4296094
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	115	109	108
2	Boot Lid	116.0	122	102	124
3	Roof	98.6	107	94	98/96
4	Left Front Fender	99.1	101	95	101
5	Left Front Door	101.3	100	107	97
6	Center Panel Left				
7	Left Rear Door	104.2	98	102	113
8	Left Back Panel	106.3	110	103	106
9	Right Front Fender	100.6	101	100	101
10	Right Front Door	104.0	101	107	104
11	Center Panel Right				
12	Right Rear Door	103.3	101	102	107
13	Right Back Panel	100.3	100	98	103

Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>A</b>	<b>Exterior Evaluation :</b>	<b>B</b>
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
No Lto plate, with spare tire, with jack and tools,1key, no warranty booklet, scratches on headlight and taillight