

General Information

Date & Time: 10, Jan, 2026 18:38

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	8,585
Registration No.	NES2827	Chassis No.	PA1B18F39M4163464
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.2	106	103	98
2	Boot Lid	108.3	112	102	111
3	Roof	97.0	97	101	91/99
4	Left Front Fender	109.0	112	107	108
5	Left Front Door	93.8	93	93	95
6	Center Panel Left				
7	Left Rear Door	95.6	100	94	94
8	Left Back Panel	106.9	112	109	100
9	Right Front Fender	99.2	100	101	97
10	Right Front Door	99.6	95	102	102
11	Center Panel Right				
12	Right Rear Door	102.6	101	103	104
13	Right Back Panel	105.9	100	103	115

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	A
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>		<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
With Lto plate.,with warranty booklet, 1key, no spare tire, no jack and tools, scratches on headlight and taillight