

General Information

Date & Time: 05, Jan, 2026 18:06

Make	Toyota	Model	Hilux
YOM	2022	Odo Meter Reading	104,718
Registration No.	CBD9525	Chassis No.	MR0JB8DD7N3188707
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	109	125	109
2	Boot Lid	94.5	101	88	95
3	Roof	98.1	107	90	108/88
4	Left Front Fender	93.4	95	89	96
5	Left Front Door	91.3	89	93	92
6	Center Panel Left				
7	Left Rear Door	88.7	88	87	92
8	Left Back Panel	91.6	93	84	98
9	Right Front Fender	100.8	105	103	94
10	Right Front Door	89.2	90	92	86
11	Center Panel Right				
12	Right Rear Door	90.1	88	87	95
13	Right Back Panel	95.7	104	83	100

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	E
<p> a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain </p>		<p> A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap </p>	
<p>Remarks</p> <p>Ceiling - Grime - Small / (L) Front Floor Mat - Missing - Yes / (R) Front Trim - Grime - Small / Mat Other - Missing - Yes / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small</p>		<p>Remarks</p> <p>(R) Front Fender, Molding - Scratch & Dent - Medium / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Medium / (R) Side Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Rear Gate - Scratch - Medium / (L) Side Gate - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch & Dent - Medium / Roof - Scratch & Dent - Small / (R) Front Tyre - Crack, Cut - Yes / (L) Front Tyre - Crack, Cut - Yes</p>	
Frame Evaluation :		Functional Evaluation :	
A		A	
<p>Remarks</p> <p>Defects not found</p>		<p>Remarks</p> <p>Defects not found</p>	

Inspector Notes
<p>With Lto plate, with warranty booklet, with spare tire and jack, 2keys, no tools, scratches on headlight and taillight, stain and traces of adhesive on vehicle,</p>