

General Information

Date & Time: 05, Jan, 2026 15:19

Make	Toyota	Model	Innova
YOM	2024	Odo Meter Reading	13,114
Registration No.	CCA8264	Chassis No.	PA2JAE8MXR0142543
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	100	109	102
2	Boot Lid	91.0	93	90	91
3	Roof	86.4	86	84	90/85
4	Left Front Fender	91.4	95	94	85
5	Left Front Door	89.7	91	93	86
6	Center Panel Left				
7	Left Rear Door	92.2	98	95	84
8	Left Back Panel	92.1	90	92	94
9	Right Front Fender	87.4	79	89	93
10	Right Front Door	86.3	84	85	91
11	Center Panel Right				
12	Right Rear Door	92.7	89	98	92
13	Right Back Panel	91.3	89	90	95

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Dashboard - Traces of Adhesive Tape - Yes / Overall Interior - Smell - Yes / (L) Front Trim - Grime - Large / (R) Front Trim - Grime - Medium / (L) Front Floor Mat - Missing - Yes</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Medium / Member (Bolted) - Dent - Yes / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>no jack and tools/ no warranty booklet/with LTO plate and sparetire/</p>