

General Information

Date & Time: 08, Jan, 2026 15:50

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	17,327
Registration No.	CCG3712	Chassis No.	PA1B18F39R4264849
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	109	117	104
2	Boot Lid	97.6	106	88	99
3	Roof	96.6	108	94	96/89
4	Left Front Fender	99.1	101	97	100
5	Left Front Door	98.5	100	102	94
6	Center Panel Left				
7	Left Rear Door	104.0	104	104	104
8	Left Back Panel	101.6	107	99	99
9	Right Front Fender	100.0	101	103	96
10	Right Front Door	96.6	96	100	94
11	Center Panel Right				
12	Right Rear Door	102.7	109	98	101
13	Right Back Panel	97.8	87	98	109

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Minimal / Mat Other - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with spare tire and jack, 3keys, no tools, fender light issue,battery weak</p>