

## General Information

Date & Time: 05, Jan, 2026 15:46

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	17,880
<b>Registration No.</b>	CCG4019	<b>Chassis No.</b>	PA1B18F32R4264529
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>114.0</b>	116	116	110
2	Boot Lid	<b>108.6</b>	110	102	114
3	Roof	<b>100.1</b>	107	91	107/96
4	Left Front Fender	<b>101.1</b>	97	104	103
5	Left Front Door	<b>99.3</b>	100	102	96
6	Center Panel Left				
7	Left Rear Door	<b>97.5</b>	101	96	96
8	Left Back Panel	<b>103.6</b>	109	101	101
9	Right Front Fender	<b>106.6</b>	109	104	107
10	Right Front Door	<b>102.6</b>	101	105	102
11	Center Panel Right				
12	Right Rear Door	<b>103.9</b>	104	99	109
13	Right Back Panel	<b>105.6</b>	100	101	116

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	A	<b>Exterior Evaluation :</b>	C
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Rear Seat - Grime - Small</p>		<p><b>Remarks</b> (R) Front Fender, Molding - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
With Lto plate, with warranty booklet, with spare tire and jack, 1key, no tools, scratches on headlight and taillight