

General Information

Date & Time: 05, Jan, 2026 11:14

Make	Toyota	Model	Lite Ace
YOM	2025	Odo Meter Reading	13,386
Registration No.	NJA7639	Chassis No.	MHKB3FE10RK005378
CC	1.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Cargo
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	54.6	52	67	45
2	Boot Lid	55.2	52	70	44
3	Roof	49.5	48	42	47/62
4	Left Front Fender	51.3	43	51	60
5	Left Front Door	48.9	54	49	44
6	Center Panel Left				
7	Left Rear Door	50.4	49	53	50
8	Left Back Panel	55.2	50	58	58
9	Right Front Fender	53.6	49	49	63
10	Right Front Door	47.0	46	45	51
11	Center Panel Right				
12	Right Rear Door	51.8	52	49	55
13	Right Back Panel	58.0	71	54	49

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Carpet - Repair Mark - Yes	Remarks (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (L) Step, In-panel, Side Spoiler - Dent - Large / (R) Step, In-panel, Side Spoiler - Dent - Medium / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate and warranty booklet / with spare tire and jack/ incomplete tools/