

General Information

Date & Time: 07, Jan, 2026 14:30

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	22,551
Registration No.	CCG1102	Chassis No.	PA1B18F33R4280383
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.0	129	109	125
2	Boot Lid	110.3	106	107	118
3	Roof	102.7	105	102	100/104
4	Left Front Fender	102.7	105	99	104
5	Left Front Door	101.0	103	100	100
6	Center Panel Left				
7	Left Rear Door	111.0	116	110	107
8	Left Back Panel	113.3	123	109	108
9	Right Front Fender	111.6	109	109	117
10	Right Front Door	105.8	113	100	105
11	Center Panel Right				
12	Right Rear Door	107.6	101	105	117
13	Right Back Panel	109.3	102	105	121

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Cut, Crack - Medium / Ceiling - Grime - Minimal</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with jack and incomplete tools/with 2 spare key/with reverse camera/with warranty booklet/with spare tire</p>