

General Information

Date & Time: 07, Jan, 2026 11:06

Make	Toyota	Model	Hiace
YOM	2023	Odo Meter Reading	24,503
Registration No.	NIM7444	Chassis No.	JTFPA9AP4P8032349
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.6	128	125	124
2	Boot Lid	127.0	122	119	140
3	Roof	133.2	144	141	116/132
4	Left Front Fender	144.3	133	149	151
5	Left Front Door	136.3	130	143	136
6	Center Panel Left	142.6	140	135	153
7	Left Rear Door				
8	Left Back Panel	125.6	122	124	131
9	Right Front Fender	133.0	136	137	126
10	Right Front Door	129.6	121	130	138
11	Center Panel Right	141.3	143	138	143
12	Right Rear Door	136.6	148	128	134
13	Right Back Panel	128.3	130	131	124

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Grime - Minimal / Ceiling - Grime - Minimal / Rear Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Center Panel - Scratch - Small / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with warranty and manual booklet, with spare tire, with incomplete tools and jack, no reverse camera, no spare key, scratches on taillight, rear seat missing.</p>