

General Information

Date & Time: 06, Jan, 2026 15:07

Make	Chevrolet	Model	Orlando
YOM	2015	Odo Meter Reading	77,474
Registration No.	NAD8141	Chassis No.	KL1YA7551FK002742
CC	1.8	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.6	118	130	105
2	Boot Lid	129.6	123	134	132
3	Roof	113.7	110	117	115/113
4	Left Front Fender	119.0	107	128	122
5	Left Front Door	125.6	123	129	125
6	Center Panel Left				
7	Left Rear Door	122.3	123	123	121
8	Left Back Panel	122.3	126	133	108
9	Right Front Fender	117.0	124	108	119
10	Right Front Door	123.3	125	126	119
11	Center Panel Right				
12	Right Rear Door	121.3	122	118	124
13	Right Back Panel	126.6	110	135	135

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Small / Steering Wheel - Worn, Peel, Crack - Medium / Dashboard - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Medium / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Minimal</p>	<p>Remarks Bonnet - Repair Traces - Yes / Bonnet, Headlight - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Roof - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 1 spare key/No reverse camera/with warranty booklet/with jack and No tools audio radio volume issue</p>