

General Information

Date & Time: 08, Jan, 2026 12:56

Make	Toyota	Model	Hiace
YOM	2019	Odo Meter Reading	114,626
Registration No.	NBE9105	Chassis No.	JTFJT02P3J5018932
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	134.0	131	154	117
2	Boot Lid	138.6	107	185	124
3	Roof	114.0	102	97	123/134
4	Left Front Fender	119.6	111	121	127
5	Left Front Door	110.0	107	105	118
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	108.7	111	99	116
9	Right Front Fender	132.6	124	135	139
10	Right Front Door	112.0	119	109	108
11	Center Panel Right	116.6	116	120	114
12	Right Rear Door	120.6	122	110	130
13	Right Back Panel	113.3	111	112	117

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Floor Mat - Grime - Small / Ceiling - Grime - Large / (L) Front Floor Mat - Cut, Crack - Medium / (R) Front Seat - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Medium</p>		<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Door, Molding - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Crack, Gap - Large / Roof - Scratch - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	D
<p>Remarks Defects not found</p>		<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Brake Pedal - Function - Weak / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>Crack front and rear bumper. Plate light issue. Brake pedal issue. Aftermarket foglight issue. With warranty booklet and spare tire. Without jack, tools and seat cover. 1 key. With LTO plate.</p>