

General Information

Date & Time: 16, Jan, 2026 12:37

Make	Toyota	Model	Hiace
YOM	2022	Odo Meter Reading	241,877
Registration No.	GAW4108	Chassis No.	JTFNAFAP4N8023945
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	243.0	253	249	227
2	Boot Lid	142.0	132	129	165
3	Roof	159.0	145	148	203/140
4	Left Front Fender	193.0	186	208	185
5	Left Front Door	189.3	183	174	211
6	Center Panel Left	202.0	188	221	197
7	Left Rear Door				
8	Left Back Panel	191.3	210	170	194
9	Right Front Fender	186.3	175	193	191
10	Right Front Door	185.3	179	171	206
11	Center Panel Right	204.6	199	219	196
12	Right Rear Door	182.0	181	179	186
13	Right Back Panel	192.6	193	179	206

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Large / Mat Other - Missing - Yes / Ceiling - Grime - Large / Steering Wheel - Worn, Peel, Crack - Large / Sunvisor, Sunglass Holder - Grime - Small / Trim Other - Grime - Small / Trim Other - Grime - Small / (L) Front Seat - Grime - Small	Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Center Panel - Repair Traces - Yes / (L) Rear Fender, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Medium / (L) Center Panel - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Large / (R) Mirror - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Center Panel - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Medium / Roof - Repair mark - Yes / Overall Exterior - Faded(Color, Gloss) - Yes
Frame Evaluation : B	Functional Evaluation : C
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
ABS warning lamp on. Battery for replacement. Engine oil for replacement. Without warranty booklet, jack and tools. With spare tire. Incomplete seat cover. 1 key. No LTO plate.