

General Information

Date & Time: 13, Jan, 2026 14:51

Make	Toyota	Model	Hiace
YOM	2022	Odo Meter Reading	284,436
Registration No.	GAW3779	Chassis No.	JTFNAFAP0N8023960
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	261.3	278	237	269
2	Boot Lid	217.3	207	215	230
3	Roof	207.5	181	209	222/218
4	Left Front Fender	242.3	264	239	224
5	Left Front Door	234.6	245	225	234
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	196.3	214	183	192
9	Right Front Fender	956.3	537	1,192	1,140
10	Right Front Door	272.0	284	266	266
11	Center Panel Right	279.6	307	307	225
12	Right Rear Door	296.6	326	294	270
13	Right Back Panel	222.3	219	222	226

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Possible flooding. Battery for replacement. Engine oil for replacement. Shift knob missing. Aircon issue. rear seat knob missing. Power window switch both side issue. Crack and gap at front and rear bumper. Without warranty booklet, spare tire, jack and tools. With seat cover. 1 key. With LTO plate.