

General Information

Date & Time: 14, Jan, 2026 11:27

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	29,606
Registration No.	NHM3636	Chassis No.	MHKU3FE10PK005681
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	62.9	75	62	52
2	Boot Lid	73.0	76	56	87
3	Roof	52.3	42	51	58/58
4	Left Front Fender	53.3	59	46	56
5	Left Front Door	51.4	53	54	47
6	Center Panel Left	63.6	70	61	61
7	Left Rear Door				
8	Left Back Panel	73.0	83	64	72
9	Right Front Fender	60.9	65	60	58
10	Right Front Door	56.8	51	56	63
11	Center Panel Right	59.7	62	63	54
12	Right Rear Door				
13	Right Back Panel	88.2	86	78	100

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Cut, Crack - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / Roof - Scratch & Dent - Medium / (R) Side Gate - Scratch - Medium / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Side Gate - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with spare tire, with jack and tools, 1key, no warranty booklet, scratches on headlights and taillights, battery weak