

## General Information

Date & Time: 15, Jan, 2026 05:34

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	19,334
<b>Registration No.</b>	GBJ6587	<b>Chassis No.</b>	PA1B18F3XS4287238
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	109	103	125
2	Boot Lid	103.9	99	100	113
3	Roof	94.1	101	91	95/90
4	Left Front Fender	96.8	98	100	94
5	Left Front Door	99.9	98	104	98
6	Center Panel Left				
7	Left Rear Door	96.3	103	96	90
8	Left Back Panel	110.3	105	118	108
9	Right Front Fender	91.9	94	91	91
10	Right Front Door	101.1	98	106	100
11	Center Panel Right				
12	Right Rear Door	105.0	103	103	109
13	Right Back Panel	104.0	96	100	116

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Cut, Crack - Small / (R) Front Trim - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Medium / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Minimal / Ceiling - Grime - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal</p>	<p><b>Remarks</b> (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch &amp; Dent - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>No LTO plate/with spare tire/No spare key/with jack and incomplete tools/with reverse camera/No warranty booklet /with seat cover</p>