

General Information

Date & Time: 15, Jan, 2026 12:49

Make	Mitsubishi	Model	Mirage
YOM	2024	Odo Meter Reading	13,091
Registration No.	KAR7897	Chassis No.	PAEA13TJRPA019040
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	137.0	139	133	139
2	Boot Lid	114.3	117	121	105
3	Roof	102.5	98	110	102/100
4	Left Front Fender	106.3	110	106	103
5	Left Front Door	106.3	110	106	103
6	Center Panel Left				
7	Left Rear Door	105.6	116	103	98
8	Left Back Panel	112.6	117	114	107
9	Right Front Fender	103.5	100	106	105
10	Right Front Door	112.6	111	112	115
11	Center Panel Right				
12	Right Rear Door	106.0	101	106	111
13	Right Back Panel	116.0	120	112	116

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	D	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Minimal / Ceiling - Grime - Small / Rear Seat - Grime - Large / Mat Other - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes</p>		<p>Remarks (L) Rear Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	C
<p>Remarks Defects not found</p>		<p>Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
Aircon blower issue. With warranty booklet and spare tire. Without jack, tools and seat cover. 1 key. No LTO plate.