

General Information

Date & Time: 21, Jan, 2026 13:44

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	12,752
Registration No.	NKQ5314	Chassis No.	PAHACACA7S6425047
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.6	103	105	109
2	Boot Lid	60.5	59	60	63
3	Roof	115.0	118	117	122/103
4	Left Front Fender	99.3	98	103	97
5	Left Front Door	95.3	93	95	98
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	74.2	60	94	68
9	Right Front Fender	102.0	97	100	109
10	Right Front Door	96.8	94	99	97
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	70.4	62	75	74

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Defects not found</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch - Small / Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Side Gate - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / Roof - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with jack and spare tire, 2keys, no tools, scratches on headlights and taillights</p>