

General Information

Date & Time: 19, Jan, 2026 16:27

Make	Toyota	Model	Innova
YOM	2024	Odo Meter Reading	17,526
Registration No.	CCD3014	Chassis No.	PA2JA8EM3R0140603
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	116	121	110
2	Boot Lid	103.7	97	109	105
3	Roof	89.5	85	85	98/91
4	Left Front Fender	101.0	91	111	101
5	Left Front Door	103.7	101	112	98
6	Center Panel Left				
7	Left Rear Door	102.3	99	102	106
8	Left Back Panel	106.3	105	109	105
9	Right Front Fender	101.5	100	108	97
10	Right Front Door	99.7	92	109	98
11	Center Panel Right				
12	Right Rear Door	97.9	101	95	98
13	Right Back Panel	104.8	97	106	111

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Head Light, High Beam - Issue - Yes</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, 2keys, with spare tire and jack, no tools,cover under the engine missing, moisture inside front headlight, scratches on headlights and taillights</p>