

General Information

Date & Time: 19, Jan, 2026 19:07

Make	Suzuki	Model	Carry
YOM	2025	Odo Meter Reading	22,868
Registration No.	NKG1887	Chassis No.	MHYD61T5SJ212132
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	122	107	116
2	Boot Lid	163.3	170	153	167
3	Roof	99.2	108	102	96/91
4	Left Front Fender	119.6	119	125	115
5	Left Front Door	109.0	105	112	110
6	Center Panel Left	119.3	134	121	103
7	Left Rear Door				
8	Left Back Panel	139.3	125	136	157
9	Right Front Fender	114.3	107	121	115
10	Right Front Door	107.3	105	111	106
11	Center Panel Right	107.5	89	113	121
12	Right Rear Door				
13	Right Back Panel	157.6	192	128	153

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Ceiling - Grime - Medium	Remarks (R) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Center Panel - Scratch - Minimal / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Roof - Scratch & Dent - Medium / Rear Gate - Scratch - Small / (L) Side Gate - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Center Panel - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Front Panel - Scratch & Dent - Minimal / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
With Lto plate, with spare tire, 2keys, no warranty booklet, no jack and tools, scratches on headlights and taillights