

General Information

Date & Time: 16, Jan, 2026 17:55

Make	Toyota	Model	Vios
YOM	2020	Odo Meter Reading	66,300
Registration No.	NFX7349	Chassis No.	PA1B18F30L4115401
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	116	113	112
2	Boot Lid	119.6	122	111	126
3	Roof	103.0	103	103	100/106
4	Left Front Fender	90.5	95	88	89
5	Left Front Door	98.6	100	96	100
6	Center Panel Left				
7	Left Rear Door	98.0	105	95	95
8	Left Back Panel	109.6	112	107	110
9	Right Front Fender	111.0	115	108	110
10	Right Front Door	115.6	119	113	115
11	Center Panel Right				
12	Right Rear Door	115.6	110	114	123
13	Right Back Panel	114.0	109	108	125

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Modified - Medium / (R) Step, In-panel, Side Spoiler - Modified - Medium / (L) Step, In-panel, Side Spoiler - Modified - Medium / Trunk Hood, Rear Gate - Modified - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Modified - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With Lto plate, with spare tire, 2keys, no warranty booklet, no jack and tools, scratches on headlights and taillights, battery weak</p>