

General Information

Date & Time: 19, Jan, 2026 15:58

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	132,816
Registration No.	NFE9338	Chassis No.	PA1B18F33N4189172
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.1	108	96	103
2	Boot Lid	178.0	181	175	178
3	Roof	102.3	108	108	93/100
4	Left Front Fender	103.6	115	96	100
5	Left Front Door	308.0	723	108	93
6	Center Panel Left				
7	Left Rear Door	106.2	99	109	111
8	Left Back Panel	108.0	118	105	101
9	Right Front Fender	101.7	107	100	98
10	Right Front Door	112.3	106	118	113
11	Center Panel Right				
12	Right Rear Door	108.6	105	112	109
13	Right Back Panel	147.0	175	142	124

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Trunk Room - Worked - Minimal / (R) Front Seat - Grime - Medium</p>		<p>Remarks (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with warranty and manual booklet, with spare tire, no tools & jack, no spare key, no reverse camera, scratches on taillight and headlight.