

General Information

Date & Time: 20, Jan, 2026 19:13

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	30,817
Registration No.	NFR3842	Chassis No.	PA1B18F31R4252887
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	137.6	128	150	135
2	Boot Lid	103.0	102	101	106
3	Roof	98.7	100	97	94/104
4	Left Front Fender	95.9	99	95	95
5	Left Front Door	96.6	98	96	96
6	Center Panel Left				
7	Left Rear Door	95.3	100	94	92
8	Left Back Panel	100.6	102	103	97
9	Right Front Fender	100.5	105	97	100
10	Right Front Door	103.6	105	100	106
11	Center Panel Right				
12	Right Rear Door	106.6	100	104	116
13	Right Back Panel	109.3	107	100	121

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Large / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Large</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Dent - Large / (L) Rear Door, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Dent - Small / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>no warranty booklet and tools/ with spare tire and jack/ with LTO plate/</p>