

General Information

Date & Time: 21, Jan, 2026 11:04

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	44,367
Registration No.	DBQ2652	Chassis No.	PA1B18F38R4269055
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	108	108	113
2	Boot Lid	110.6	108	101	123
3	Roof	98.3	101	101	93/98
4	Left Front Fender	107.0	113	109	99
5	Left Front Door	99.2	99	102	97
6	Center Panel Left				
7	Left Rear Door	102.5	107	103	98
8	Left Back Panel	113.3	115	112	113
9	Right Front Fender	116.3	102	101	146
10	Right Front Door	102.7	108	105	95
11	Center Panel Right				
12	Right Rear Door	101.3	103	101	100
13	Right Back Panel	102.6	99	100	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Overall Interior - Smell - Yes / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Minimal / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Medium / Ceiling - Cigarette Burns - Burnt, Hole / Ceiling - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal</p>	<p>Remarks Member (Bolted) - Dent - Yes / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Crack, Gap - Large / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet, jack, and tools, with spare tire, with LTO plate, possible flooding, scratches on tail light</p>