

General Information

Date & Time: 21, Jan, 2026 11:28

Make	Mitsubishi	Model	Xpander
YOM	2024	Odo Meter Reading	28,912
Registration No.	DBN9325	Chassis No.	MK2LRNC1WRN00226
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.0	89	99	95
2	Boot Lid	165.6	117	111	269
3	Roof	96.7	110	87	97/92
4	Left Front Fender	80.6	82	80	80
5	Left Front Door	86.7	86	87	88
6	Center Panel Left				
7	Left Rear Door	91.1	91	90	93
8	Left Back Panel	103.5	100	106	105
9	Right Front Fender	77.7	76	77	80
10	Right Front Door	92.6	97	89	92
11	Center Panel Right				
12	Right Rear Door	89.8	92	90	88
13	Right Back Panel	108.5	135	97	94

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Ceiling - Grime - Medium	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with warranty booklet, with spare tire, 1key, no jack and tools, scratches on headlights and taillights, warning lamp on