

General Information

Date & Time: 20, Jan, 2026 16:14

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	23,444
Registration No.	EAL1069	Chassis No.	PA1B18F34S4285100
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.0	130	109	139
2	Boot Lid	162.3	156	146	185
3	Roof	126.5	119	179	104/104
4	Left Front Fender	111.0	111	110	112
5	Left Front Door	97.6	101	95	97
6	Center Panel Left				
7	Left Rear Door	144.3	145	144	144
8	Left Back Panel	113.3	121	105	114
9	Right Front Fender	109.6	111	112	106
10	Right Front Door	102.2	106	101	100
11	Center Panel Right				
12	Right Rear Door	111.3	105	110	119
13	Right Back Panel	108.1	111	100	114

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Medium / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Medium / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch - Medium / Roof - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with spare tire, with incomplete tools and jack, with reverse camera, with manual booklet, issue on taillight, scratches on headlight.</p>